



Full calorie drinks are not dispensing

TROUBLESHOOTING GUIDE

HERE IS WHAT TO DO!




HFCS
(High Fructose Corn Syrup)


Is the HFCS BIB empty?

IF YES, replace HFCS BIBs.


STILL HAVING TROUBLE, TRY THESE STEPS




Clean BIB connectors.



Verify CO₂ tank pressure is above 100 PSIG.



Check for kinked or pinched tubing from the HFCS BIB.



Prime HFCS from the dashboard.



Pour and taste test a full-calorie beverage (Coca-Cola or HiC).

STILL NOT RESOLVED, CONTACT US

Visit the web portal at

myCoke.com/ESPortal

Or contact a dedicated
Coca-Cola Service Technician at

IN THE U.S.

1 (800) 241-COKE (2653)

IN CANADA

1 (800) 318-COKE (2653)